

# WATER WELL REPORT

STATE OF WASHINGTON

Start Card No. 58443

Water Right Permit No. 98019

(1) OWNER: Name Jack Tabor Address 13318 322nd Ave. NE Duvall, WA

(2) LOCATION OF WELL: County Stevens E 1/2 NW & Sec 27 T. 33 N., R. 40 W.M.

(2a) STREET ADDRESS OF WELL (or nearest address)

(3) PROPOSED USE:  Domestic  Irrigation  DeWater  Industrial  Test Well  Municipal  Other

(4) TYPE OF WORK: Owner's number of well (if more than one)  
 Abandoned  New well  Deepened  Reconditioned   
 Method: Dug  Cable  Rotary  Bored  Driven  Jetted

(5) DIMENSIONS: Diameter of well 6 inches.  
 Drilled 160 feet. Depth of completed well 160 ft.

(6) CONSTRUCTION DETAILS:  
 Casing installed: 6 Diam. from +1 ft. to 159 ft.  
 Welded  Liner installed  Threaded

Perforations: Yes  No   
 Type of perforator used \_\_\_\_\_  
 SIZE of perforations \_\_\_\_\_ in by \_\_\_\_\_ in.  
 \_\_\_\_\_ perforations from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.  
 \_\_\_\_\_ perforations from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.  
 \_\_\_\_\_ perforations from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.

Screens: Yes  No   
 Manufacturer's Name \_\_\_\_\_  
 Type \_\_\_\_\_ Model No. \_\_\_\_\_  
 Diam. \_\_\_\_\_ Slot size \_\_\_\_\_ from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.  
 Diam. \_\_\_\_\_ Slot size \_\_\_\_\_ from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.

Gravel packed: Yes  No  Size of gravel \_\_\_\_\_  
 Gravel placed from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.

Surface seal: Yes  No  To what depth? 18 ft.  
 Material used in seal Bentonite  
 Did any strata contain unusable water? Yes  No   
 Type of water? \_\_\_\_\_ Depth of strata \_\_\_\_\_  
 Method of sealing strata off \_\_\_\_\_

(7) PUMP: Manufacturer's Name \_\_\_\_\_  
 Type \_\_\_\_\_ HP \_\_\_\_\_

(8) WATER LEVELS: Land surface elevation above mean sea level \_\_\_\_\_ ft.  
 Static level 100 ft. below top of well Date \_\_\_\_\_  
 Artesian pressure \_\_\_\_\_ lbs. per square inch Date \_\_\_\_\_  
 Artesian water is controlled by \_\_\_\_\_ (Cap. valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level  
 Was a pump test made? Yes  No  If yes, by whom? \_\_\_\_\_  
 Yield \_\_\_\_\_ gal/min with \_\_\_\_\_ ft. drawdown after \_\_\_\_\_ hrs.

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test \_\_\_\_\_


Water test \_\_\_\_\_ gal/min with \_\_\_\_\_ ft. drawdown after \_\_\_\_\_ hrs.  
 Artest 10-12 gal/min with stem set at 155 ft. for 1 hrs.

Artesian flow \_\_\_\_\_ gpm Date \_\_\_\_\_  
 Temperature of water \_\_\_\_\_ Was a chemical analysis made? Yes  No

(10) WELL LOG or ABANDONMENT PROCEDURE DESCRIPTION

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of information.

MATERIAL	FROM	TO
Sand & gravel	0	110
Moist, sandy clay	110	155
Brocken rock, water	155	160



Work started 7/14 19 92 Completed 7/14 19 92

**WELL CONSTRUCTOR CERTIFICATION:**  
 I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief.

NAME FOGLE PUMP & SUPPLY INC.,  
 (PERSON FIRM OR CORPORATION) (TYPE OR PRINT)

Address 316 W. 5th Colville, WA 99114

(Signed) Michael Ball License No. 1251  
 (WELL DRILLER)

Contractor's Registration No. FOGLEPS095L4 Date 7/14 19 92

(USE ADDITIONAL SHEETS IF NECESSARY)

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

